

Symphony Hills Homes Association

Pool Deck Project 2023



The Concrete has broken down over the past two decades and, in some areas, remaining was less than 1 inch thick, resulting in cracks and spalding





Parts of slabs crumbling and many small and medium cracks allowing water to cause further damage

